

NWOD Oil Sheen Prevention Plan

Kathryn Hernandez to: Hans.Millican

12/02/2005 11:46 AM

From: Kathryn Hernandez/EPR/R8/USEPA/US

To:

Cc: jmurdock@utah.gov, leclerc.russell@epa.gov, beverett@epa.gov

After reviewing the current attached Downstream Assessment Program, and the Oil Sheen Prevention Plan attached to the 12/1/05 4:16 pm email, the controls and follow up monitoring plan incorporate all the EPA requested information. The plans have been reviewed and concurred on by the State and County. You may resume work in the canal as soon as the controls are in place in the canal, with the understanding that if oil starts getting past the final boom, NWOD must reevaluate the containment measures.

Thanks.

Kathryn Hernandez
USEPA, Region VIII (8EPR-SR)
999 18th Street, Ste 300
Denver, CO 80202
(303) 312-6101 (office)
(720) 951-0974 (cell)

-----Hans.Millican@erm.com wrote: -----

To: Kathryn Hernandez/EPR/R8/USEPA/US@EPA
From: Hans.Millican@erm.com
Date: 12/02/2005 07:35AM
Subject: Re: Fw: Oil Sheen Prevention Plan

Hello Kathy,

Here is the updated Downstream Assessment Plan. I have added that the WG will cover the lab costs of the samples collected by the county and that if the additional samples collected by the County fail that the procedures for a failed confirmation sample outlined in the SAPP/QAPP be followed.

Thanks,

Hans J. Millican
ERM - Rocky Mountain Region
Salt Lake City, UT
(801) 595-8400
hans.millican@erm.com

-----Hernandez.Kathryn@epamail.epa.gov wrote: -----

To: Hans.Millican@erm.com
From: Hernandez.Kathryn@epamail.epa.gov
Date: 12/01/2005 07:37PM
Subject: Re: Fw: Oil Sheen Prevention Plan

I just reviewed the downstream assessment program and I still don't see any verbiage related to 1) NWOD paying for the sampling that the county will be conducting to verify there has not been recontamination and 2) Action by NWOD if samples exceed the established benchmarks. Am I missing something?

Kathy

Kathryn Hernandez
USEPA, Region VIII (8EPR-SR)
999 18th Street, Ste 300

Denver, CO 80202
(303) 312-6101(office)
(720) 951-0974(cell)

-----Hans.Millican@erm.com wrote: -----

To: Kathryn Hernandez/EPR/R8/USEPA/US@EPA

From: Hans.Millican@erm.com

Date: 12/01/2005 04:14PM

cc: jeff.niermeyer@slcgov.com, vicki.bennett@ci.slc.ut.us, Dave.McCarthy@bp.com,

Florence.Reynolds@ci.slc.ut.us, gwilliams@earthfax.com, garrick@chevrontexaco.com, sfuc@chevron.com,

mike.taylor@erm.com, david.wilson@erm.com

Subject: Re: Fw: Oil Sheen Prevention Plan

Hello Kathy,

Here are the two plans. Please let me know if you have any questions.

Hans J. Millican

ERM - Rocky Mountain Region

Salt Lake City, UT

(801) 595-8400

hans.millican@erm.com

This electronic mail message may contain information which is (a) LEGALLY PRIVILEGED, PROPRIETARY IN NATURE, OR OTHERWISE PROTECTED BY LAW FROM DISCLOSURE, and (b) intended only for the use of the Addressee (s) names herein. If you are not the Addressee (s), or the person responsible for delivering this to the Addressee (s), you are hereby notified that reading, copying, or distributing this message is prohibited. If you have received this electronic mail message in error, please contact us immediately at (303) 741-5050 and take the steps necessary to delete the message completely from your computer system.

Thank you.

Please visit ERM's web site: <http://www.erm.com>

[attachment "Oil Sheen Prevention Plan.pdf" removed by Kathryn Hernandez/EPR/R8/USEPA/US]

[attachment "Downstream Assesment Program.pdf" removed by Kathryn

Hernandez/EPR/R8/USEPA/US]  - DownstreamAssesmentProgram.doc